
COASTAL PHOTOGRAPH BY PER BRUUN




PHOTO 168. Erosion on Danfuskie Island, South Carolina, has made extensive inroads on a maritime forest. Destruction of the forest is caused by undermining of the root systems, salt-water intrusion, and eventual windfall of weakened trees. (Photo: Per Bruun, 34 Baynard Cove Road, Hilton Head, South Carolina. 10 June 1989).